

SNUPPS

Standardized Nuclear Unit
Power Plant System

5 Choke Cherry Road
Rockville, Maryland 20850
(301) 869-8010

Nicholas A. Petrick
Executive Director

March 20, 1980

SLNRC 80- 15 FILE: 0278.10
SUBJ: IE Bulletin No 80-03: Loss of
Charcoal from Standard Type II,
2 Inch, Tray Adsorber Cells

Mr. Boyce Grier
Director, Region I
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406


Docket Nos.: STN 50-482, STN 50-483, STN 50-485, STN 50-486

Dear Mr. Grier:

This letter is submitted in response to the subject IE Bulletin for the SNUPPS Utilities, Kansas Gas and Electric Company, Union Electric Company and Rochester Gas and Electric Corporation.

Charcoal adsorber cells have not been shipped to any SNUPPS site. The adsorber cells planned for use in the SNUPPS plants are of a different design and manufacturer than the type described in the Bulletin.

Very truly yours,


Nicholas A. Petrick

RLS/vas

cc: Mr. James G. Keppler, Director, Region III, USNRC
Mr. Karl V. Seyfrit, Director, Region IV, USNRC
Director, Division of Fuel Facility and Materials Safety Inspection,
Office of Inspection and Enforcement, USNRC, Washington D.C. 20555