



8005060225

ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

April 30, 1980

1-040-20

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Comm.
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

SUBJECT: Arkansas Nuclear One-Unit 1
Docket No. 50-313
License No. DPR-51
Licensee Event Report No. 80-009/03L-0
(File: 0520)

Gentlemen:

In accordance with Arkansas Nuclear One Unit 1 Technical Specification 6.12.3.2.b, attached is the subject report concerning the lead hydrogen purge fan, VSF-30A, that tripped on overload due to the stuck check valve, HPA-5, on the suction of the fan. Due to a mailing problem this LER is being processed late. Hopefully, this delay will not occur again.

Very truly yours,

David C. Trimble

David C. Trimble
Manager, Licensing

DCT:GAC:lp

Attachment

cc: Mr. Victor Stello, Jr., Director ✓
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Comm.
Washington, D. C. 20555

Mr. Norman M. Haller, Director
Office of Management and Program Analysis
U.S. Nuclear Regulatory Comm.
Washington, D. C. 20555

A002
S
/11