

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A | R | A | N | O | 1 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5

7 8 9 14 15 25 26 57 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE JO CAT 58

CON'T

01 | L | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 1 | 3 | 0 | 3 | 2 | 8 | 8 | 0 | 0 | 4 | 3 | 0 | 8 | 1 | 0 | 9

7 8 60 61 68 69 74 75 80

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During normal power operation, while performing a surveillance test, the

03 | lead hydrogrn purge supply fan, VSF-30A, tripped on overload. The

04 | standby hydrogen purge system remained operable. The problem was found

05 | to be a stuck check valve (HPA-5) on the suction of the fan. The valve

06 | was returned to operable status by freeing the valve and completing a

07 | successful surveillance test on the fan. This occurrence is similar to

08 | LER's 50-313/77-009 & 78-016. Reportable per T.S. 6.12.3.2(b).

09 | S | E | E | D | V | A | L | V | E | X | C | A

7 8 9 10 11 12 13 14 15 16 17 18 19 20

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

17 | 8 | 10 | 0 | 1 | 9 | 0 | 3 | L | 0

21 22 23 24 25 26 27 28 29 30 31 32

LER/NO REPORT NUMBER EVENT YEAR SHUTDOWN METHOD SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

18 | B | F | Z | Z | 0 | 0 | 0 | 0 | N | Y | A | N | 0 | 1 | 0

33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUR PRIME COMP SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Investigation revealed the cause of the stuck check valve to be corrosion

11 | due to the seal water leaking onto the supply check valve when the unit

12 | was not running. Preventive maintenance was performed on the 3 similar

13 | valves in the hydrogen purge system. A design change to isolate the

14 | seal water from the fans when not needed has been initiated.

15 | E | 1 | 1 | 0 | 0 | NA | B | Surveillance Test

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

16 | Z | Z | NA | NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

17 | 0 | 0 | 0 | Z | NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

18 | 0 | 0 | 0 | Z | NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PERSONNEL INJURIES NUMBER DESCRIPTION

19 | 0 | 0 | 0 | NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

20 | Z | NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PUBLICITY ISSUED DESCRIPTION

20 | N | NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF PREPARER L. S. Bramlett

PHONE 501/968-2519