(412) 456-6000



Pittsburgh, Pa.

May 1, 1980

United States Nuclear Regulatory Commission Region I 631 Park Avenue King of Prussia, PA 19406

Attention: Mr. Boyce H. Grier

Director

Subject: Beaver Valley Power Station - Unit No. 2

Final Report - Cable Tray Galvanizing Deficiency

Docket No. 50-412

Significant Deficiency Report No. 80-01

Gentlemen:

Enclosed, herewith, is the final report showing the results of our investigation of the T. J. Cope Company Quality Control Inspection Program of Galvanized Cable Trays. This final report is in reference to the potentially reportable deficiency in cable tray galvanizing under the provisions of 10CFR50.55 (e) (1) (i) reported to the Nuclear Regulatory Commission by H. A. VanWassen of the Duquesne Light Company on February 7, 1980. An interim report was subsequently sent to the Nuclear Regulatory Commission by the Duquesne Light Company on March 10, 1980.

Duquesne Light Company will continue to inspect all tray refore installation, and those already installed. In addition, ... uquesne Light Company vendor surveillance group will inspect all tray until confidence is restored in the vendor's inspection program.

DUQUESNE LIGHT COMPANY

Vice President

Enclosure

cc: Messrs. V. Stello (15)

W. G. McDonald