

## SNUPPS

Standardized Nuclear Unit  
Power Plant System

5 Choke Cherry Road  
Rockville, Maryland 20850  
(301) 869-8010

Nicholas A. Petrick  
Executive Director

March 20, 1980

SLNRC 80- 12 FILE: 0491.10.2  
SUBJ: Undetectable Failure in Engineered  
Safety Features Actuation System

Mr. Boyce Grier  
Director, Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Docket Nos.: STN 50-482, STN 50-483, STN 50-485, STN 50-486


Reference: (1) SLNRC 79-21, dated 12/6/79: Same subject  
(2) Westinghouse letter (T.M. Anderson), NS-TMA-2204, to USNRC  
(V. Stello, Jr.), dated 2/15/80: Same subject

Dear Mr. Grier:

Reference (1) reported a potential deficiency involving the Engineered Safety Features Actuation System and described a test sequence that was the necessary corrective action applicable to the SNUPPS plants. Reference (2) provided the NRC with revised tests that yield more conclusive results.

The SNUPPS utilities are investigating hardware changes that may preclude the need for the tests described in Reference (2). If such hardware changes are not feasible, the appropriate test sequence from Reference (2) will be incorporated in the procedures for the SNUPPS plants.

Very truly yours,

  
Nicholas A. Petrick

RLS/vas

cc: Mr. James G. Keppler, Director, Region III, USNRC  
Mr. Karl V. Seyfrit, Director, Region IV, USNRC  
Mr. Victor Stello, Jr., Director, Office of Inspection and Enforcement,  
USNRC, Washington D.C.