

8005070455
S

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

May 1, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNIT 2 - OVERSTRESSED U-BOLTS ON 3/4-INCH
DRAIN LINES - NCR SQN SWP 8007 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
N. Merriweather on April 1, 1980, in accordance with 10 CFR 50.55(e).
We consider 10 CFR 21 applicable to this nonconformance. Enclosed
is our final report.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 654-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

POOR ORIGINAL

B019
SE
1/1