

Georgia Power Company  
230 Peachtree Street  
Post Office Box 4545  
Atlanta, Georgia 30302  
Telephone 404 522-6060

8005070465 Q



Georgia Power

the southern electric system

Power Generation Department

May 1, 1980

United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II - Suite 3100  
101 Marietta Street, NW  
Atlanta, Georgia 30303

REFERENCE:  
RII - JPO  
50-321/50-366  
I&E Bulletin 80-02

ATTENTION: Mr. James P. O'Reilly

Gentlemen:

The Georgia Power Company hereby submits the following revision to our letter dated April 16, 1980, which responded to I&E Bulletin 80-02, "Inadequate Quality Assurance For Nuclear Supplied Equipment".

Revised Response to Question 1a

Reactor feedwater spargers and thermal sleeves manufactured by Marvin Engineering Company are currently installed at E. I. Hatch, Unit 1. Subject spargers and thermal sleeves were supplied by its NSSS supplier, General Electric Company (GE), San Jose, California. Unit 2 feedwater spargers were not manufactured by Marvin Engineering Company.

All subsequent references to Unit 2 feedwater spargers and thermal sleeves should be disregarded. A re-examination of the Unit 2 feedwater sparger documentation package, after receiving comments from GE, indicated that the spargers were not, in fact, fabricated by Marvin Engineering. We regret this oversight.

If you have any questions in regards to this information revision, please contact my office.

Sincerely yours,

*W. A. Widner, S. L. F. 1*

W. A. Widner  
Vice President and General Manager  
Nuclear Generation

JAE/mb

xc: Director of the Office of Inspection and Enforcement  
Director of the Division of Operating Reactors, Office of  
Nuclear Reactor Regulation ✓

*Acc'd 5/10*