

NARRATIVE REPORT

Georgia Power Company
Plant E. I. Hatch
Baxley, Georgia 31513

Reportable Occurrence Report No. 50-321/1980-037.

While the reactor was in the run mode at 2415 MWt, it was discovered that the Post Loca Monitors had not been calibrated before their last possible date of 4/5/80. Upon discovery the Post Loca Monitors were calibrated on 4/8/80 and were acceptable. A similar event was reported on LER 50-321/1980-027. There was no effect upon public health or safety.

The cause of this event and the previous one was attributed to personnel oversight. The same individual was involved in both cases. A personnel change has been made to help prevent any future occurrence.

The generic review revealed that missed or late surveillance has been a problem in the past. Numerous changes have been made in the scheduling and tracking of surveillance. We feel that the system we now have is adequate and the proper selection of personnel in the surveillance area should resolve the problem.