

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

8005130423

5

May 2, 1980

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE
REPORT SQHO-50-327/3034

The subject reportable occurrence was telocopied to you on April 22,
1980. A subsequent evaluation by the Plant Operations Review Committee
has shown that this occurrence was reportable under 10CFR50.72 but was
not reportable under Sequoyah technical specification since the occurrence
only involved inadvertent initiation of the safety injection signal.
This event occurred on Sequoyah unit 1.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun
Director of Nuclear Power

cc: Director
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavallee
Nuclear Safety Analysis Center
Palo Alto, California 94303

Mr. W. T. Cottle, NRC Inspector, Sequoyah

A002
3/10

POOR ORIGINAL