

LER #: 50-366/1980-070
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-366

Narrative Report
for LER 50-366/1980-070

On 4-22-80, with the reactor in the run mode, while performing procedure HNP-2-3405, RCIC Pump Operability, the trip and throttle valve went closed when the RCIC turbine reached approximately 2000 rpms. The trip and throttle valve was reset, and the pump operability was performed satisfactorily. The cause of the trip and throttle valve closing was not identified. This is not a repetitive event.

Concurrently when the RCIC trip and throttle valve went closed, the 2E41-F002 HPCI steam supply inboard isolated. Ref. to RO No. 50-366/1980-068.