

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
230 PEACHTREE STREET, N. W. SUITE 818
ATLANTA, GEORGIA 30303

In Reply Refer To:
IE:II:TNE
50-269/75-4
50-270/75-4
50-287/75-4

APR 30 1975

Duke Power Company
ATTN: Mr. A. C. Thies, Senior
Vice President
Production and Transmission
Power Building
422 South Church Street
Charlotte, North Carolina 28242

Gentlemen:

This refers to the inspection conducted by Mr. T. N. Epps of this office on April 1-3, 1975, and by Mr. G. R. Jenkins on April 8-11, 1975, of activities authorized by NRC Operating License Nos. DPR-38, 47, and 55 for the Oconee facility, and to the discussion of our findings held with Mr. J. W. Hampton at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspector.

We have also examined actions you have taken with regard to previously identified enforcement matters and unresolved items. The status of these items is identified in Sections II and IV of the summary of the enclosed report.

During the inspection, it was found that certain activities under your license appear to be in noncompliance with NRC requirements. These items and references to pertinent requirements are listed in Section I of the summary of the enclosed report.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within 20 days of your receipt of this notice, a written statement or explanation in reply including: (1) corrective steps which have



7911280 600

APR 30 1975

Duke Power Company

-2-

been taken by you, and the results achieved; (2) corrective steps which will be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. In that corrective actions were previously reviewed, no additional response is requested to noncompliance item I.B.2.

You are also requested to inform us of the date when a final solution to the reactor coolant system pressure transmitter calibration problem will be implemented.

Other infractions identified through your internal audit program and which were corrected, or corrective action was initiated, are set out in the enclosed inspection report. No additional information is needed for these items at this time.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you submit a written application to this office requesting that such information be withheld from public disclosure. If no proprietary information is identified, a written statement to that effect should be submitted. If an application is submitted, it must fully identify the bases for which information is claimed to be proprietary. The application should be prepared so that information sought to be withheld is incorporated in a separate paper and referenced in the application since the application will be placed in the Public Document Room. Your application, or written statement, should be submitted to us within 20 days. If we are not contacted as specified, the enclosed report and this letter may then be placed in the Public Document Room.


APR 30 1975

Duke Power Company

-3-

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Very truly yours,



Norman C. Moseley
Director

Enclosure:

IE Inspection Report Nos.
50-269/75-4, 50-270/75-4 and
50-287/75-4

cc w/encl:

J. E. Smith, Manager
P. O. Box 1175
Seneca, South Carolina 29678