

DUKE POWER COMPANY  
POWER BUILDING  
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

TELEPHONE: AREA 704  
373-4083

March 14, 1980


Mr. J. P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: Catawba Nuclear Station  
Units 1 and 2  
Docket Nos. 50-413 and 50-414

Dear Mr. O'Reilly:

On February 14, 1980, Duke Power Company reported a construction deficiency to Mr. C. R. McFarland of your office. This deficiency concerned the containment equipment hatch at Catawba. Our written report on this deficiency will be submitted on or before April 4, 1980.

Very truly yours,

  
William O. Parker, Jr.

ROS:vr

cc: Director,  
Office of Inspection and Enforcement



B019  
SE  
1/0

5

8008210 509