

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

8005050 172

APR 1 7 1980

0

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Richard P. Crouse
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the inspection conducted March 26-28, 1980, by Messrs. A. G. Finley and J. P. Patterson of this office and to the discussion of our findings with Mr. T. Murray, Plant Superintendent and other members of his staff at the conclusion of the inspection. The inspection was a review of activities at the Davis-Besse Nuclear Power Station authorized by NRC License No. NPF-3 and Title 10, Code of Federal Regulations. Part 70.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described in the enclosed Appendix A. The inspection showed that action had been taken to correct the identified noncompliance and to prevent recurrence. Consequently, no reply to this noncompliance is required and we have no further questions regarding this matter at this time.

Areas examined during the inspection concern a subject matter which is exempt from disclosure according to Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Consequently, our report of this inspection will not be placed in the Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

J. A. Hind, Chief Safeguards Branch

Enclosures:

- Appendix A, Notice of Violation
- Property 2.790(d) Information
 Property 2.790(d) Information

cc w/encl:

Mr. T. D. Murray, Station Superintendent Central Files Reproduction Unit NRC 20b

cc w/o encl: PDR Local PDR