

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

May 29, 1980

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE NUCLEAR PLANT UNIT A1 - REPORTABLE DEFICIENCY - RPV SHIELD  
WALL - WELD DEFICIENCIES (NCR HNP-A-087)

Initial report of the subject deficiency was made to R. W. Wright, NRC-OIE, Region II, on February 15, 1980. The first interim report was submitted on March 13, 1980. In compliance with paragraph 50.55(e) of 10 CFR Part 50, we are enclosing the second interim report of the subject deficiency. TVA anticipates transmitting the final report on or before September 26, 1980. If you have any questions regarding this matter, please call Jim Domer at FTS 857-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Boia  
5/11

8006040230 S