

2-1-81 50/305

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE BOX 784

COLUMBIA, SOUTH CAROLINA 29218

E. H. CREWS, JR.
VICE-PRESIDENT AND GROUP EXECUTIVE
ENGINEERING AND CONSTRUCTION

May 28, 1980


Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street
Atlanta, Georgia 30305

Subject: Virgil C. Summer Nuclear Station
Reportable Significant Deficiency
Inadequate Electrical Separation
Nuclear Engineering File 3.1051

Dear Mr. O'Reilly:

On 4/30/80, a significant deficiency, as defined by 10CFR50.55(e), was reported to NRC resident inspector Jack Skolds on a DC power circuit from a safety related panel to a non-safety related panel with no isolation device. Details of the deficiency and corrective action are provided in the attachment. This is considered the final report on the deficiency.

Very truly yours,


E. H. Crews, Jr.

JAW:EHC:rh

cc: H. T. Babb
E. H. Crews, Jr.
O. S. Bradham
D. R. Moore
H. Radin
J. Skolds
V. C. Summer
NPCF/Dixon
File
Document Management Branch
Washington, D. C.

8006050042
S

Boig
5/1