TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

411 9 All: 19

May 21, 1980

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta street Atlanta, Georgia 30303

Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 80-02 - RII: JPO 50-518, -519, -520, -521, -553, -554 - HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS ALL UNITS

In response to your January 21, 1980, letter which transmitted OIE Bulletin 80-02, our investigations reveal that feedwater spargers or thermal sleeves manufactured and/or fabricated by the Marvin Engineering Company have not been purchased and/or have not been installed in our Hartsville or Phipps Bend Nuclear Plants. If you have any questions regarding this subject, please call Jim Domer at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager

Nuclear Regulation and Safety

L, M, Mills by Rhs