

MICHIGAN STATE UNIVERSITY

COLLEGE OF ENGINEERING • DIVISION OF ENGINEERING RESEARCH

EAST LANSING • MICHIGAN • 48824

May 1, 1980

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Docket 50-294

Gentlemen:

The item of non-compliance noted by Mr. Ron Paul is, by its very nature, impossible to correct since the temporal sequence of events for 1979 has been determined. The Reactor Safety Committee regrets the two month lapse and intends to avoid similar situations in the future by placing more emphasis on scheduling controls. Meetings subsequent to November 19, 1979, have been timely and hopefully they will continue to be so. Any questions should be directed to James Carrick, Reactor Supervisor, at (517) 353-9097.

Sincerely,

*Stephen A. Terry*  
Stephen A. Terry  
Assistant Vice President for Finance

*James T. Carrick*  
James T. Carrick  
Reactor Supervisor

JC/bm

MAY 12 1980

80 06090 515