



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION II - SUITE 818
230 PEACHTREE STREET, NORTHWEST
ATLANTA, GEORGIA 30303

TELEPHONE: 526-4537

December 18, 1970

J. P. O'Reilly, Chief, Reactor Inspection and Enforcement Branch
Division of Compliance, Headquarters

DUKE POWER COMPANY (OCONEE 2 AND 3), LICENSE NOS. CPPR-34 AND 35,
DOCKET NOS. 50-270 AND 287

Attached CO Report Nos. 50-270, 287/70-7 covering a routine inspection on
November 23-25, 1970, is forwarded for information. There were no sig-
nificant problems identified. Several isolated cases of minor QC concern
were observed; however, unless these persist, no Compliance action will
be anticipated. In general, we believe performance by the licensee con-
tinues to be satisfactory.

T. J. Long

Senior Reactor Inspector

CO:II:FJL

Enclosure:

CO Rpt. Nos. 50-270, 287/70-7
(Brownlee, Cochran)

cc w/encl:

E. G. Case, DRS (3)
P. A. Morris, DRL
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)
P. W. Howe, DRL (2)
A. Giambusso, CO
L. Kornblith, Jr., CO
R. H. Engelken, CO
R. W. Kirkman, CO:I
E. H. Grier, CO:III
J. W. Flora, CO:IV
R. W. Smith, CO:V

REG Files

7911270 459

Q