

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION V

SUITE 202, WALNUT CREEK PLAZA
1990 N. CALIFORNIA BOULEVARD
WALNUT CREEK, CALIFORNIA 94596


SEP 17 1975

H. D. Thornburg, Chief, Field Coordination and Enforcement Branch
Office of Inspection and Enforcement, Headquarters

SACRAMENTO MUNICIPAL UTILITY DISTRICT (RANCHO SECO)
DOCKET NO. 50-312

The attached report by our field inspector of a visit to the subject facility on September 2-5, 1975 is forwarded for information.

We consider the licensee's corrective action in response to the enforcement item described in IE Inspection Report No. 50-312/75-05 to be effectively implemented. A recent internal audit by the SMUD QA organization found the administrative control of jumpers and bypasses to be fully implemented consistent with the licensee's procedural requirements.


J. L. Crews, Chief
Reactor Testing and Operations Branch

Enclosure:
IE Inspection Report
No. 50-312/75-08



8002210602