NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 58401

June 12, 1980

Mr J G Keppler Office of Inspection & Enforcement U S Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

RCIC Control Problem

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.b. in that this condition led to operation in a degraded mode permitted by limiting condition for operation Specification 3.5.F.2.

Yours very truly,

L O Mayer, PE Manager of Nuclear Support Services

LOM/JAG/ak

cc: Director, IE, USNRC 30)

Director, MIPC, USNRC (3)

MPCA

Attn: J W Ferman