



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

June 25, 1980

1-060-19

Mr. Norman M. Haller, Director
Office of Management and Program
Analysis
U. S. Nuclear Regulatory Comm.
Washington, D. C. 20555

Subject: Arkansas Nuclear One - Unit 1
Docket No. 50-313
License No. DPR-51
Monthly Operating Report - Correction
(File: 2-0520.1)

Gentlemen:

Attached are corrections to the subject report for May, 1980. The correction to the unit shutdowns and power reductions portion of the subject report indicates the License Event Report number for the reactor coolant pump seal failure outage.

Very truly yours,

David C. Trimble

David C. Trimble
Manager, Licensing

DCT:DVH:skm

Attachment

cc: Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Comm.
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Mr. Victor Stello, Jr., Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Comm.
Washington, D. C. 20555

*Acob
5,11*

8007010470 R