



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

July 3, 1980

D. L. ASWELL
Vice President-Power Production

LPL 14473
Q-3-A35.07.17
Q-3-A35.02.01

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: WATERFORD SES UNIT NO. 3
DOCKET NO. 50-382
INTERIM REPORT OF SIGNIFICANT
CONSTRUCTION DEFICIENCY NO. 17
"BASE METAL DEFECTS IN MAIN STEAM AND FEEDWATER
CONTAINMENT PENETRATION ANCHORS"

REFERENCE: Telcon - L. L. Bass (LP&L) to R. Hall (NRC) on June 10, 1980

Dear Mr. Seyfrit:

In accordance with the requirements of 10CFR50.55(e), we are hereby providing two copies of the Interim Report of Significant Construction Deficiency No. 17, "Base Metal Defects in Main Steam and Feedwater Containment Penetration Anchors".

If you have any questions, please advise.

Very truly yours,

D. L. Aswell

LLB:pr

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
(with 15 copies of report)
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
(with 1 copy of report)

*Boia
S, 11*

8007080234