

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

NOV 20 378

Docket No. 50-346

IE FILE COPY

Toledo Edison Company ATTN: Mr. James S. Grant Vice President - Energy Supply Edison Plaza 300 Madison Avenue Toledo, OH 43652

Gentlemen:

This refers to the inspection conducted by Messrs. T. N. Tambling and J. Smith of this office on August 28-31, September 27-29, October 31, and November 1, 1978, of activities at Davis-Besse Nuclear Power Station, Unit 1, authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with Mr. T. Murray and bers of your staff at the conclusion of the inspection and telephone discussion between Mr. Knop of this office and Mr. Murray on November 16, 1978.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described in the enclosed Appendix A. The inspection showed that action had been taken to correct the identified noncompliance and to prevent recurrence. Consequently, no reply to this noncompliance is required and we have no further questions regarding this matter at this time.

8001220 895 Q

Toledo Edison Company - 2 -

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Gaston Fiorelli, Ch.ef Reactor Operations end Nuclear Support Iranch

Enclosures: 1. Appendix A. Notice of Violation

2. IE Inspection Report No. 50-346/78-26

cc w/encls: Mr. T. D. Murray, Station Superintendent Central Files Reproduction Unit NRC 20b PDR Local PDR NSIC TIC U. Young Park, Power Siting Commission

OFFICE	RIII	RIII	RIII	RIII	RIII
	Tambling/bEk	Knop ACH	Smith	Streeter	Florelli
	11/16/78		"/16/78	11/16/78	17/78