

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

April 22, 1975

K. V. Seyfrit, Chief, Technical Assistance Branch,  
Office of Inspection and Enforcement, Headquarters

THRU: *GF* G. Fiorelli, Chief, Reactor Operations Branch

TOLEDO EDISON COMPANY (DAVIS-BESSE 1)  
DOCKET NO. 50-346  
ABSENCE OF MISSILE PROTECTION BWS TANK

Attached is a copy of Mr. R. D. Martin's letter requesting a review of the adequacy of the missile protection of the Borated Water Storage Tank at Davis-Besse. Please review and coordinate any required changes with Licensing.

*RC Knop*  
R. C. Knop  
Senior Reactor Inspector  
Projects Unit 1

Enclosure:  
As Stated

cc: J. G. Davis, IE:HQ, w/encl  
R. F. Warnick, IE:HQ, w/encl  
J. G. Keppler, IE:HQ, w/encl  
IE Files  
DR Central Files



8001 290659