



UNITED STATES  
ATOMIC ENERGY COMMISSION  
WASHINGTON, D.C. 20545

MAY 8 1973

D. F. Knuth, RO

REQUEST FOR SUPPLEMENTARY INSPECTION EFFORT

The enclosed memo, Thomas to Keppler dated 5/1/73, describes a deficiency identified at Oconee 1, and the corrective action taken. The memo (page 3) also identifies 6 sites (8 units) which will require similar corrective action, and recommends (page 4) regional followup to verify that corrective action has been taken. We concur in that recommendation and suggest that you so advise the appropriate regional offices.

*JH*  
J. B. Henderson, RO

Enclosure: As stated.

cc:

R. H. Engelken, RO  
J. G. Keppler, RO  
G. W. Reinmuth, RO

8001310 464