Shopping .

From: J. L. Crews, IE: I

PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE -- PN-76-

POSSIBLE safety or public interest significance. The information presented is as initially received without verification or evaluation and is basically all that is known by OIE staff as of program on date of this notification. IT SHOULD BE SPECIFICALLY NOTED THAT THIS NOTIFICATION MAY CONTAIN INFORMATION THAT LATER MAY BE DETERMINED TO BE INACCURATE OR INCONSISTENT. AN OFFICE OF INSPECTION AND ENFORCEMENT MOTIFICATION OF AN INCIDENT OR OCCURRENCE (BLUE SHEET) SUBSEQUENTLY WILL BE ISSUED IF WARRANTED.

Facility: Sacramento Municipal Utility District (Rancho Seco)

Subject: OUTAGE EXTENSION - GENERATOR INSULATION BREAKDOWN

An insulation breakdown in a phase I stator coil of the main generator was identified during the past weekend. The generator rotor will have to be removed to permit stator repairs. Repairs are expected to take two weeks if only re-insulation is required. If stator coil replacement is required, repairs may take an additional two months.

The facility was in the final phases of preparation for returning to power operation following completion of the turbine repair outage which had commenced on June 30, 1975.

THE LIGENSE PLAN PETITION THE LOCAL NEWS MEDIA OF THE OCCUPANCE.

OIE (Region V - San Francisco) received notification of this occurrence by telephone from the Plant Technical Assistant at 09:00 a.m. on January 12, 1976.

RFW

Roy

Davis
POOR
ORIGINAL