



HELPING BUILD ARKANSAS IE FILE COPY

ARKANSAS POWER & LIGHT COMPANY

P.O. BOX 551 LITTLE ROCK, ARKANSAS 72203 • (501) 371-4000

June 3, 1977

1-067-4

Mr. E. Morris Howard, Director
Office of Inspection & Enforcement
Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive Suite 1000
Arlington, Texas 76011



Subject: Arkansas Nuclear One-Unit 1
Docket No. 50-313
License No. DPR-51
Reportable Occurrence Report 50-313/77-12
(File: 0520)

Gentlemen:

In accordance with Technical Specification 6.1.2.3.2, we have attached the subject report concerning a leak at a downstream pipe-to-pipe weld in the high discharge piping to the Spent Fuel Pool.

Should additional information be needed, please advise.

Very truly yours,

Donald A. Rueter
Manager, Licensing

DAR:REI:tw

Attachment

cc: Mr. W. D. MacDonald, Director
Office of Management Information
and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dr. E. Volgenau, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8004110 830
S

