

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 A R A N 0 2 0 0 - 0 0 0 0 - 0 0 4 1 1 1 1 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CON'T

01 L 0 5 0 0 0 3 1 6 8 7 0 6 0 2 8 0 0 6 2 7 8 0 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

REPORT SOURCE: 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During Mode 1 operation, the Steam Driven Emergency Feedwater Pump (2P7A)
03 tripped on overspeed following a manual start. The electric emergency
04 feedwater pump (2P7B) was verified to be operable. This occurrence is
05 similar to LER's 50-368/79-055, 79-072, 79-081, 79-104, 80-022 and 80-030.
06 Reportable per Tech Spec 6.9.1.9(b).
07
08
09

SYSTEM CODE W B 11 CAUSE CODE B 12 CAUSE SUBCODE A 13 COMPONENT CODE T U R B I N 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16

LER NO. 17 REPORT NUMBER 8 0 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

ACTION TAKEN E 13 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPD-4 FORM SUB Y 24 PRIME COMP SUPPLIER A 25 COMPONENT MANUFACTURER 1 4 7 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 Investigation did not reveal cause of pump trip. Pump will be tested
11 frequently until resolution to the trip problem is made. Vendor has been
12 contacted and will assist in determining the cause of the overspeed trips.
13
14

FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS Power Ops 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Control Room Indication 32

ACTIVITY CONTENT Z 33 Z 34 NA 35 NA 36 LOCATION OF RELEASE NA 37

PERSONNEL EXPOSURES NUMBER 0 0 0 38 TYPE Z 39 DESCRIPTION NA 40

PERSONNEL INJURIES NUMBER 0 0 0 41 DESCRIPTION NA 42

LOSS OF OR DAMAGE TO FACILITY TYPE Z 43 DESCRIPTION NA 44

PUBLICITY ISSUED N 45 DESCRIPTION NA 46

NAME OF PREPARER Rex Pendergraft PHONE 501/968-2519

NRC USE ONLY

8007080178