

**Bronson**  
METHODIST HOSPITAL

252 East Lovell Street  
Kalamazoo, Michigan 49007  
(616) 383-7654

40-8056

June 27, 1980

Ms. Barbara G. Brooks  
Licensee Operation Evaluation Branch  
Division of Technical Support  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Re: License No. 21-13125-01  
License No. SUB-1045  
Bronson Methodist Hospital

Dear Ms. Brooks:

Enclosed is our report on personnel monitoring for the calendar year 1979 as is required by Paragraph 20.407, 10 CFR-20. I am sending two copies.

Please note that in your memorandum dated November 20, 1979 it was indicated that a report sent to you by our hospital on 3/28/79 for 1978 was not received for the "license number on the label of the attached form". Perhaps, since only one license number was listed on our report, the query was meant for a second license number. In any case, please consider that the report sent last year was for both the 21-13125-01 license and for the SUB-1045 license. I did not think you could have been wanting a report on SUB-1045, since it is for an enriched Uranium shield located inside our linear accelerator where no one other than myself has access to it.

Anyway, the enclosed 1979 report has listed both licenses as indicated above.

Cordially,

*Charles S. Simons*

Charles S. Simons, Ph. D.  
Radiation Safety Supervisor

- cc: ✓ 1) USNRC Document Management Branch  
2) Mr. McConnell, V. Pres. Administration

*Noor  
5/11*

8007080 273

*C*