

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	L	T	N	I	S	N	P	1	0	0	-	0	0	1	0	1	0	-	0	0	0	4	1	1	1	1	1	0	1	1	0	1	1	0
----	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CONT

01	L	0	5	1	0	0	1	0	1	2	7	0	1	5	3	1	1	8	0	5	0	1	6	1	2	1	7	8	1	0	5
----	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 70 81 82 83 84 85 86 87 88 89 80 91 92 93 94 95 96 97 98 99 90 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (P)

01 Upon preoperational testing of unit 2 safety injection pumps it was found
 02 that the 6900-V breakers would lock-out preventing pump start if they were
 03 given a close signal for > 0.32 seconds when a trip condition existed.
 04 There is no indication to operations when this "locked-out" condition
 05 exists. The breaker appears to be available for service when it actually
 06 is not. The only means of clearing the condition is to remove and reinstall
 07 the fuses at the breaker or manually change the state of relays 4X and 3013.

	SYNTHETIC CODE	CAUSE CODE	STATE CODE	COM- MUNICATE	TIME CODE	STATE CODE
01	Z 1 Z	0	A 6 0	C K I J R P R K J G	B	Z
02	REPORT NUMBER	EVENT YEAR	EFFECT NUMBER	OPERATING PERIOD	OPERATING YEAR	OPERATING YEAR
03	8 1 0	1	0 1 4 0	1	1 9 1 1	1
04	ACTION TAKEN	EFFECT NUMBER	STATE ON	OPERATING PERIOD	OPERATING YEAR	OPERATING YEAR
05	Z 0 1 X	Z 0	Z 0	0 0 0 0 0	N/A	N/A

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (P)

01 Engineering Design has been notified of this problem and is evaluating it.
 02 to determine if the functional requirements of safety related systems
 03 are jeopardized.

04

	SYNTHETIC STATUS	SYNTHETIC NUMBER	OPERATING NUMBER	OPERATING PERIOD	OPERATING YEAR	OPERATING YEAR
01	B	1 0 0 0 1	N/A	B	Preoperational Test	
02	ACTIVITY NUMBER	ACTIVITY NUMBER	ACTIVITY NUMBER			
03	Z 1	Z 1	N/A			
04	0 1 0 0 1	Z 1	N/A			
05	0 1 0 0 1					
06	Z 1					
07	0 1 0 0 1					
08	Z 1					
09	N/A					

NAME OF PREPARED _____ Dean Romine

PRINTED

8007080 288