

Anchor/Darling

Valve Company

2474 Witter Road
Hayward, CA 94545
(415) 785-2430
Telex: 335451 Ancorco

May 30, 1980

United States Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive Suite 1000
Arlington, Texas 76012

Attention: Mr. Uldis Potapovs, Chief
Vendor Inspection Branch

Docket No. 99900048/80-01

Subject: Audit of A/DV, April 21-24, 1980

Gentlemen:

This letter is in response to the notice of deviation contained in the above referenced docket file.


The Quality Assurance Manager, this writer, was required to respond to an internal audit of the Quality Assurance Division by April 20, 1980. As of April 21-24, 1980, as noted by Mr. Hunter, said response had not been prepared.

The required response was issued by this writer on April 28, 1980, referencing internal corrective actions which were implemented on April 24-25, 1980. In response to the request for corrective action to prevent recurrence, the Quality Assurance Manager, by receipt of the referenced Notice of Deviation, has been made aware of the gravity of not ensuring a timely response, and thus will make every effort to ensure that such deviation is not repeated.

Please do not hesitate to contact me if any additional information is required.

Sincerely yours,

ANCHOR/DARLING VALVE COMPANY



R.W. Swayne/jn
Quality Assurance Manager

cc: D.P. Gilbert (w/NRC letter)
J.J. Carroll (w/NRC letter)
W.G. Knecht (w/NRC letter)
NRC Audit File

8007100330