



Geotechnical Engineering Program
Civil Engineering Department

Colorado State University
Fort Collins, Colorado
80523

May 5, 1980

Mr. Glen Brown
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Dr., Suite 1000
Arlington, Texas 76011

40-8021

Dear Mr. Brown:

A trip report dated 18 April 80 was forwarded to your office concerning the placement of a PVC liner in Cell #2, Energy Fuels Nuclear (EFN), Blanding, Utah. A critical typographical error was made that must be corrected.

On page 3, paragraph h, line 3 now reads:

". . . bottom and 13" along the embankment."

and should read:

". . . bottom and 18" along the embankment."

This correction is necessary to show EFN has complied with the license conditions. The 18" cover was what was found in the field.

If you have any questions, please call me at (303)491-6707 or (303) 491-6081.

Yours very truly,

Steven R. Abt

SRA/rv

8007170 332