

71e

Telephone 617 366-9011

TWX
710-390-0739

WYR 80-68
B.4.1.1

YANKEE ATOMIC ELECTRIC COMPANY



20 Turnpike Road Westborough, Massachusetts 01581

June 18, 1980

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, PA 19406

Attention: Mr. Boyce H. Grier, Director

- References: (a) License No. DPR-3 (Docket No. 50-29)
- (b) USNRC Letter to YAEC dated April 17, 1980
I&E Bulletin No. 80-09

Dear Sir:

Subject: USNRC IE Bulletin No. 80-09; "Hydramotor Actuator Deficiencies"

As required in reference (b), we are providing the following information.

We have determined that there are no ITT General controls AH-90 or NH-90 series Hydramotor Actuators used in safety-related systems at the Yankee Atomic plant. We, therefore, plan no further action with regard to this Bulletin.

We trust that you find this information satisfactory; however, should you desire additional information, please contact us.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY

Roy E. M. Reid
 D. V. Moody *for*
 Manager of Operations

BLD/am

8007170 582

Q