

July 9, 1980

In reply, please refer to LAC-7021

DOCKET NO. 50-409

Mr. James G. Keppler
Regional Director
U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: DAIRYLAND POWER COOPERATIVE
LA CROSSE BOILING WATER REACTOR (LACBWR)
PROVISIONAL OPERATING LICENSE NO. DPR-45
IE BULLETIN AND IE CIRCULAR NO. 80-16 -
POTENTIAL MISAPPLICATION OF ROSEMOUNT, INC.
MODELS 1151 AND 1152 PRESSURE TRANSMITTERS
WITH EITHER "A" OR "D" OUTPUT CODES

Reference: (1) NRC Letter, Keppler to Linder,
dated June 27, 1980.

Dear Mr. Keppler:


In response to the IE Bulletin and Circular No. 80-16, we have determined the following:

- 1) Rosemount Inc. Models 1151 and 1152 pressure transmitters with either "A" or "D" output codes are not used in safety related or other electrical circuits at the La Crosse Boiling Water Reactor.

If there are any questions concerning this response, please contact us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE



Frank Linder, General Manager

FL:WRN:af

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operations Inspection
Washington, D. C. 20555

8007220

096