



**Commonwealth Edison**  
Zion Generating Station  
Shiloh Blvd. & Lake Michigan  
Zion, Illinois 60099  
Telephone 312/746-2084

*DBB*

July 16, 1980

Mr. James G. Keppler  
Regional Director  
Directorate of Regulatory Operations  
Region III  
U. S. Nuclear Regulatory Commission  
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station  
Docket No. 50-304/DPR-48  
Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-304/80-23 for Zion Generating Station.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2b(3), which states that observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems, require a 30-day written report.

Very truly yours,

K. L. Graesser  
Superintendent  
Zion Station

SG/wk

Enclosure: Reportable Occurrence Report No. 50-304/80-23

*A002*  
*3*  
*1/1*

8007220 587

*5*

JUL 17 1980