



UNITED STATES
ATOMIC ENERGY COMMISSION
WASHINGTON, D.C. 20545

MAR 1 1971

C. G. Long, Chief, BWR Projects Branch #2
Division of Reactor Licensing

DUKE POWER COMPANY (OCONEE 1) - CO REPORT NO. 269/71-1

The enclosed report of an inspection of the subject facility on January 5-8, 1971, is forwarded for information.

This report and the previous report, CO Report No. 50-269/70-12, provide information on an apparent generic-type failure of the ITE time delay relays. This and similar relay failures are currently being reviewed by our Technical Support Branch. We plan to forward our recommendations to you upon completion of this review.

J. P. O'Reilly for
J. P. O'Reilly, Chief
Reactor Testing and Operations
Branch
Division of Compliance

Enclosure:
CO Report No. 269/71-1

cc w/enclosure:
E. G. Case, DRS (3)
P. A. Morris, DRL
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)
P. W. Howe, DRL (2)
A. Giambusso, CO
L. Kornblith, Jr., CO
R. H. Engelken, CO
R. W. Kirkman, CO:V
B. H. Grier, CO:III
J. W. Flora, CO:IV
R. W. Smith, CO:V
W. C. Seidle, CO:II w/o encl.
Central File

7911310 684 Q