



UNITED STATES
 NUCLEAR REGULATORY COMMISSION
 REGION III
 799 ROOSEVELT ROAD
 GLEN ELLYN, ILLINOIS 60137

August 14, 1978

Creswell

56

MEMORANDUM FOR: J. F. Streeter, Chief, Nuclear Support Section 1
 FROM: J. S. Creswell, Reactor Inspector
 SUBJECT: INFORMATION FOR MANAGEMENT MEETING AT DAVIS-BESSE

Per your request I am furnishing some items to be considered for discussion during the management meeting which is to be held with Davis-Besse personnel on August 16, 1978. Specifically the following items are suggested:

1. That operating personnel be apprised in a timely manner of system modifications and that immediate operator actions required by emergency procedures be thoroughly understood.

Examples - IE Report 50-346/78-17, Paragraph 5B

2. That when personnel identify problems with operation or testing, a complete review be given to their concerns and appropriate action taken.

Example - IE Report 50-346/78-17, Paragraph 4

3. That procedures associated with power escalation be implemented.

Examples - IE Report 50-346/78-06, Paragraph 6
 IE Report 50-346/78-17, Paragraph 2, 6 and 13

4. That facility change requests for implementation be fully supported by an evaluation and any restrictions regarding implementation be understood by plant personnel.

Example - IE Report 50-346/78-17, Paragraph 5a

5. That technical evaluations be done in a timely manner. This in particular applies to conditions discovered during operation that indicate exceeding design conditions.

Example - Loss of pressurizer level condition discovered during November 29, 1977 event and effect on subsequent operation. Evaluation still underway.

J. S. Creswell
 J. S. Creswell
 Reactor Inspector

POOR ORIGINAL

cc: G. Ficorelli, T. Tumbling,
 R. C. Knop, RIII Files

8001160 723

F. G.