



January 5, 1978

Docket No. 50-346

License No. NPF-3

Serial No. 1-8

JAMES S. GRANT
Vice President
Energy Supply
(419) 259-5232

Creswell

Mr. Gaston Fiorelli, Chief
Reactor Operations and
Nuclear Support Branch
U. S. NRC Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Fiorelli:

Toledo Edison acknowledges receipt of your December 16, 1977, letter and enclosures, Appendix A and report 77-34, referencing an apparent deviation from Davis-Besse Nuclear Power Station Unit 1 commitments to the NRC, listed as a "Deviation" in Appendix A.

Following a thorough examination of the items of concern, Toledo Edison herein offers information regarding these items.

Deviation A. Contrary to the licensee's commitment in Section 3.6.2.7.1.30 of the FSAR to utilize a pressure boundary between the two auxiliary feedwater pumps, the connecting pressure boundary door was found open on October 27 and November 17, 1977.

Response

Station personnel were informed on November 17 and 18, 1977, of the requirement to keep the connecting pressure boundary door between the auxiliary feedwater pumps closed, except for passage. In addition, the following signs:

ENSURE DOOR CLOSED AND LATCHED

OPEN ONLY FOR NORMAL
TRANSIT ENTRY AND EXIT

were attached to both sides of the subject door by December 15, 1977.

Yours very truly,

J. S. Grant

JSG/WHG/cmk

8001180109