PORV OPERATION

DEMAND VALVE OPENINGS	2
FAILURE TO CLOSE	0
INADVERTENT ACTUATION	2
FAILURE TO CLOSE	1

8002100060

(T)

PORV ACTUATION

DEMAND VALVE OPENINGS		5441 70
	OPEN	FAIL TO CLOSE
HIGH PRESSURE TRIP DURING SPURIOUS		
TURBINE RUNBACK AT POWER -	1	0
HIGH PRESSURE TRIP DURING LOSS OF		
LOAD - POWER ASCENSION TEST -	1	0.
INADVERTENT ACTUATION		
RPS MAINTENANCE - SPURIOUS OPEN SIGNAL -		
PRE POWER TESTING AT HOT SHUTDOWN -	1	1
PORV MAINTENANCE - SPURIOUS OPEN SIGNAL -		
COLD SHUTDOWN -	1	0