

MEMO from:

DONNA R. GALLETLY

Unit I Change mode

7. A note indicating of meter drive EPW following loss of 4 kcal 5 or loss of P.W. power.

1. Reduce Hi Log Trip from 2390 to 2320
2. Complete the termination of all inlets to containment penetration. Hook up 16 TC's to computer
3. Provide shut signal to normal ramp discharge path on any ES
4. Review containment isolation to act upon as necessary
5. Shut selected containment isolation valves on high vibrations
6. Identify valve position indicators that are not actual position but rather ordered position

Provide indication to operator when at normal