



POOR ORIGINAL

Metropolitan Edison Company
Post Office Box 480
Middletown, Pennsylvania 17057
717 844 4041

Writer's Direct Dial Number

February 13, 1980
TLL 048

TMI Support
Attn: J. T. Collins, Deputy Director
U. S. Nuclear Regulatory Commission
c/o Three Mile Island Nuclear Station
Middletown, Pa. 17057

Dear Sir:

Three Mile Island Nuclear Station, Unit II (TMI-2)
Operating License No. DPR-73
Docket No. 50-320
HEPA/Charcoal Filter Changeout Documentation

This letter is in fulfillment of item 14 of our letter to you on December 21, 1979 (GQL 1509).

HEPA filters in the Auxiliary and Fuel Handling Building have been inspected and damaged filters have been replaced. Procedures for in-place DOP testing of the filter banks were submitted to the NRC for review and approval. We are currently awaiting NRC acceptance of our responses to questions raised by the NRC as a result of the NRC's first review.

Charcoal adsorbers in the Auxiliary Building "A" & "B" trains and in the Fuel Handling Building "A" train have been replaced. The Fuel Handling Building "B" train was not replaced and in-place freon leak tests on the replaced adsorber banks were not performed. This is due principally to the fact that the charcoal adsorbers no longer serve any real function since the quantity of radio iodine in the Auxiliary and Fuel Handling Buildings is essentially zero. The recovery Technical Specifications recognize this fact by the exclusion of charcoal adsorbers for the discussed filter banks.

Sincerely,

/s/ R. F. Wilson

R. F. Wilson
Director, TMI-II

RFW:SDC:hah

cc: R. Vollmer

ADD
S, 10

P

8002200 465