



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

TIC

March 4, 1980

Docket No. 50-2

University of Michigan  
ATTN: Dr. William Kerr, Director  
Michigan Memorial - Phoenix  
Project  
Phoenix Memorial Laboratory  
Ann Arbor, Michigan 48105

Gentlemen:

This refers to our letter dated February 25, 1980, and the attached inspection report numbered 50-002/80-01. This report should have been numbered 50-002/80-02.

Enclosed with this letter is a correctly numbered report page. Please replace the misnumbered page with the enclosed revised page. Thank you.

Sincerely,

A. B. Davis, Chief  
Fuel Facility and Materials  
Safety Branch

Enclosure: Revised Report Page  
Report No. 50-002/80-02

cc w/encl:  
Central Files  
Reproduction Unit NRC 20b  
PDR  
NSIC  
TIC

8009200 327

U.S. NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT

REGION III

Report No. 50-002/80-02

Docket No. 50-002

License No. R-28

Licensee: University of Michigan  
Michigan Memorial-Phoenix Project  
Ann Arbor, MI 48105

Facility Name: Ford Nuclear Reactor

Inspection At: Ford Nuclear Reactor Site  
Ann Arbor, MI

Inspection Conducted: January 21-23, 1980

*D. E. Miller*  
Inspectors: D. E. Miller

*R. A. Paul*  
R. A. Paul

*W. L. Fisher*  
Approved By: W. L. Fisher, Chief  
Fuel Facility Projects and  
Radiation Support Section

2-17-80

2/14/80

2/21/80

Inspection Summary:

Inspection on January 21-23, 1980 (Report No. 50-002/80-02)

Areas Inspected: Routine, unannounced inspection of radiation protection and radioactive waste programs, including: qualifications; audits; facilities; training; procedures; instruments and equipment; exposure control; surveys; effluent releases; records and reports of effluents; effluent control instrumentation; posting, labeling, and control; notification and reports; licensee action on previously identified enforcement items and commitments; and IE bulletins and circulars. The inspection involved 34 inspector-hours on site by two NRC inspectors.

Results: No items of noncompliance or deviations were identified.