



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TIC

FEB 12 1980

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Richard P. Crouse
Vice President
Energy Supply

Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the inspection conducted by Messrs. I. N. Jackiw, E. R. Swanson, and L. G. McGregor of this office on December 3-7, 11-13, and 19-20, 1979 of activities at the Davis-Besse Power Station authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with you at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as described in the enclosed Appendix A.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

As discussed with you this was a special inspection to review the effectiveness of your QA program in selected areas for both past and ongoing activities. While the items of noncompliance and unresolved items identified during this inspection taken individually, are not considered significant the examples indicate that further management attention in these areas is needed. We will continue to review the effectiveness of your QA program during future inspections.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document

P


8003270 246

FEB 12 1980

Room, except as follows. If this report contains information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



R. F. Heishman, Chief
Reactor Operations and
Nuclear Support Branch

Enclosures:

1. Appendix A, Notice of Violation
2. IE Inspection Report
No. 50-346/79-30

cc w/encls:

Mr. T. D. Murray, Station
Superintendent
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC
Harold Kohn, Power
Siting Commission
Helen W. Evans, State
of Ohio