

ENGINEERING OFFICE

TURNPIKE ROAD (R1. 9) WESTBORO, MASSACHUSETTS 01581 617-366-9011

B.3.2.1

WMY 80-56

March 21, 1980

United States Nuclear Regulatory Commission Washington, D. C. 20555

Attention: Office of Nuclear Reactor Regulation Mr. Darrell G. Eisenhut

- Reference: (a) License No. DPR-36 (Docket No. 50-309)
 - (b) NRC letter from D. G. Eisenhut to All Operating Light Water Reactors, dated November 9, 1979.
 - (c) NRC letter from D. G. Eisenhut to All Operating Light Water Reactors, dated November 27, 1979.

Dear Sir:

Our reply to your letters, Reference (b and c) requesting confirmation that information provided to you on our behalf by CE regarding the accuracy of fuel clad swelling and rupture evaluations was written on January 7, 1980. However, a review of in-house records, followed by discussions with your staff, indicate that this letter was probably not submitted. Similar letters transmitted on behalf of other Yankee plants apparently lead to the assumption that the Maine Yankee letter had indeed been submitted.

We wish to correct this oversight at this time by submitting the enclosed January 7, letter. We are not aware of any inconvenience to your staff as a result of this delay. We trust this information is satisfactory; however, if you should have any questions, please do not hesitate to contact us.

Very truly yours,

MAINE YANKEE ATOMIC POWER COMPANY

st H dwen

Robert H. Groce Senior Engineer - Licensing

RHG/smw Enclosure

8003280401