Georgia Power Company Post Office Box 4545 Atlanta, Georgia 30302 Telephone 404 522-6060

7147 2 All: 13



File: X7BG03M4

Log: GM-578

٠.

Southern Company Services, Inc Post Office Box 2625 Birmingham, Alabama 35202 Telephone 205 870-6011

425

Docket Number: 50-424/526

United States Nuclear Regulatory Commission Office of Inspection and Enforcement Region II - Suite 3100 101 Marietta Street, N.W. Atlanta, Georgia 30303

Attention: Mr. James P. O'Reilly

Reference: RII JPO 50-424, 425 Voids in Concrete Placements on Interior

Walls in the Auxiliary Building, File X7B603-M4, Log 6M-557,

letter of January 18, 1980

Gentlemen:

On December 20, 1979 it was reported to your office that a potential reportable item under 10CFR50.55(e) existed at Plant Vogtle concerning voids in concrete placements on interior walls in the auxiliary building.

Georgia Power Company has conducted a significant deficiency evaluation and an evaluation for a substantial safety hazard. It has been concluded that a significant deficiency and a substantial safety hazard did exist. Attached is the Georgia Power Company report concerning the voids in concrete placements on interior walls in the auxiliary building.

This response contains no proprietary information and may be placed in the NRC Public Documents Room upon receipt.

Doug Dutton,

Project General Manager

xc: U. S. Nuclear Regulatory Commission Attn: Victor Stello, Jr., Director Office of Inspection and Enforcement Washington, D.C. 20555

M. D. Hunt - Region II

B05,/1

United States Nuclear Regulatory Commission Attn: Mr. James P. O'Reilly Page 2

xc: J. H. Miller, Jr.
F. G. Mitchell, Jr.
R. J. Kelly
C. F. Whitmer
R. E. Conway
D. E. Dutton
J. T. Beckham, Jr.
R. Staffa
K. M. Gillespie
L. T. Gucwa
C. R. Miles, Jr.
E. D. Groover
D. L. McCrary
R. A. Thomas
O. Batum
J. A. Bailey
M. Z. Jeric

B. L. Lex R. H. Pinson