

APPENDIX ANOTICE OF VIOLATION

South Carolina Electric and Gas Company
V. C. Sumner

License No. CPPR-94

Based on the NRC inspection January 22-25, 1980, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by Criterion V of Appendix B to 10 CFR 50 and implemented by the FSAR, Paragraph 17.1.5, "Activities affecting quality shall be prescribed by documented instructions, procedures,...and shall be accomplished in accordance with those instructions, procedures,..." GAI Specification SP-545-044461-000 (with revisions through June 12, 1979) requires ultrasonic examination of ASME Section III Class 1 pipe in accordance with AEC Regulatory Guide 1.66.

Contrary to the above, on December 19, 1979, piping installed in an ASME Section III, Class 1 application had not been ultrasonic examined to the AEC Regulatory Guide 1.66 requirement. The identity and location of this pipe are described in DCC Nonconformance Notice 1194.

This is an infraction.