



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

8005140045

TERA

APRIL 25 1980

Docket No. 50-245

Mr. W. G. Council, Vice President  
Nuclear Engineering and Operations  
Northeast Nuclear Energy Company  
P. O. Box 270  
Hartford, Connecticut 06101

Dear Mr. Council

SUBJECT: EFFECT OF A DC POWER SUPPLY FAILURE ON ECCS PERFORMANCE

It has generally been recognized that the loss of a direct current (DC) power supply could disable several emergency core cooling system components and thereby could result in a limiting single failure condition for some breaks. The enclosed letter report was submitted to the NRC staff by the General Electric Company to provide a definitive, generic, reference analysis of the effects of DC power supply failures on ECCS conformance calculations. The NRC staff is reviewing the analysis which compares the peak cladding temperatures associated with various postulated DC power supply failure (ECCS equipment availability) cases to the peak cladding temperatures for a HPCI (small break) failure and LPCI injection valve (large break) failure cases. Since the study was based on plant design information which may have been incomplete or out-of-date, some uncertainty exists whether the worse ECCS system availability combinations have been identified for your operating BWRs. Accordingly, in order that we may have an adequate level of assurance that the systems combinations assumed in the generic analysis are conservative for Millstone Nuclear Power Station, Unit No. 1, we request that you confirm the conclusion of the reference study regarding the minimum ECCS equipment availability with a DC power supply failure. Include in your response a list of the ECCS equipment that would be available for large and small (1) recirculation loop discharge breaks, and (2) recirculation loop suction breaks. The listing of equipment available should take into account not only DC power supply failure, but also loss of equipment due to water spillage.

Please provide a schedule for your response within 30 days of the receipt of this letter.


Mr. W. G. Council

- 2 -

APRIL 25 1980

This request for generic information was approved by GAO under clearance number B-180225(579018); this clearance expires October 31, 1980.

Sincerely,



Thomas A. Ippolito, Chief  
Operating Reactors Branch #3  
Division of Operating Reactors

Enclosure:

General Electric Company letter  
(R. E. Engel) to USNRC (P. S.  
Check), "DC Power Source Failure  
for BWR/3 and 4," dated November 1,  
1978.

cc w/enclosure:  
See next page

cc

William H. Cuddy, Esquire  
Day, Berry & Howard  
Counselors at Law  
One Constitution Plaza  
Hartford, Connecticut 06103

Anthony Z. Roisman  
Natural Resources Defense Council  
917 15th Street, N. W.  
Washington, D. C. 20005

Northeast Nuclear Energy Company  
ATTN: Superintendent  
Millstone Plant  
P. O. Box 128  
Waterford, Connecticut 06385

Mr. James R. Himmelwright  
Northeast Utilities Service Company  
P. O. Box 270  
Hartford, Connecticut 06101

Resident Inspector  
c/o U. S. NRC  
P. O. Box Drawer KK  
Niantic, Connecticut 06357

Waterford Public Library  
Rope Ferry Road, Route 156  
Waterford, Connecticut 06385

First Selectman of the Town  
of Waterford  
Hall of Records  
200 Boston Post Road  
Waterford, Connecticut 06385

Connecticut Energy Agency  
ATTN: Assistant Director  
Research and Policy  
Development  
Department of Planning and  
Energy Policy  
20 Grand Street  
Hartford, Connecticut 06106

Director, Technical Assessment  
Division  
Office of Radiation Programs  
(AW-459)  
U. S. Environmental Protection  
Agency  
Crystal Mall #2  
Arlington, Virginia 20460

U. S. Environmental Protection  
Agency  
Region I Office  
ATTN: EIS COORDINATOR  
JFK Federal Building  
Boston, Massachusetts 02203