



800514055

Westinghouse Electric Corporation

Power Systems

Switchgear Division

700 Braddock Avenue
East Pittsburgh Pennsylvania 15112

January 22, 1980

U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Drive, Suite 1000
Arlington, Texas 76012

Attention: Mr. U. Potapovs, Chief
Vendor Inspection Branch

Docket No. 99900330/79-01

Gentlemen:

Your letter of December 17, 1979 to Mr. D. M. Sauter transmitted the report of the findings of the Quality Program inspection performed by Mr. J. R. Agee on November 27-29, 1979. The following is our response to the specific deviation noted in Mr. Agee's report:

We are now in the process of reviewing our existing procedures for control of records. We are also evaluating alternative approaches for meeting the retention and protection requirements. We are examining the programs of other Westinghouse divisions involved with similar concerns, e.g., we have met with representatives of the Nuclear Technology Division to study their program and to obtain their guidance.

By April 1, 1980 we will have a plan and schedule for improvement of our records program. By September 1, 1980 we will have the required new procedures documented and implemented.

Yours truly,

E. I. Stahr, Manager
Quality Assurance
Switchgear Division

/fc

Approved by:


D. M. Sauter



Westinghouse Electric Corporation

Power Systems

Switchgear Division

700 Braddock Avenue
East Pittsburgh Pennsylvania 15112

January 22, 1980

U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Drive, Suite 1000
Arlington, Texas 76012

Attention: Mr. U. Potapovs, Chief
Vendor Inspection Branch

Docket No. 90900330/79-01

Gentlemen:

Your letter of December 17, 1979 to Mr. D. M. Sauter transmitted the report of the findings of the Quality Program inspection performed by Mr. J. R. Agee on November 27-29, 1979. The following is our response to the specific deviation noted in Mr. Agee's report:

We are now in the process of reviewing our existing procedures for control of records. We are also evaluating alternative approaches for meeting the retention and protection requirements. We are examining the programs of other Westinghouse divisions involved with similar concerns, e.g., we have met with representatives of the Nuclear Technology Division to study their program and to obtain their guidance.

By April 1, 1980 we will have a plan and schedule for improvement of our records program. By September 1, 1980 we will have the required new procedures documented and implemented.

Yours truly,

H. I. Stahr, Manager
Quality Assurance
Switchgear Division

/fc

Approved by: *D. M. Sauter*
D. M. Sauter



EXECUTIVE CORRESPONDENCE

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76012

Packet No. 99900330/79-01

Westinghouse Electric Corp.
Switchgear Division
Attn: Mr. D. M. Sauter
Division Manager
700 Braddock Avenue
East Pittsburgh, PA 15112

Gentlemen:

Thank you for your letter of January 22, 1980, in response to our letter dated December 17, 1979, with an enclosure. We have no further questions at this time. We will review your corrective action during a future inspection.

EV

I agree the response is inadequate

- ① We should require that we address fire protection as a specific issue
- ② We should inform ~~them~~ that while full implementation by Sept 1 may be acceptable, that for that to be so, they must define some interim program to ensure that appropriate records are being retained & that reasonable protection is afforded.

KW



EXECUTIVE CORRESPONDENCE

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76012

cket No. 99900330/79-01

Westinghouse Electric Corp.
Switchgear Division
Attn: Mr. D. M. Sauter
Division Manager
700 Braddock Avenue
East Pittsburgh, PA 15112

Gentlemen:

Thank you for your letter of January 22, 1980, in response to our letter dated December 17, 1979, with an enclosure. We have no further questions at this time. We will review your corrective action during a future inspection.

EV

I agree the response is inadequate
① We should require that W address fire protection as a specific issue
② We should inform them that while full implementation by Sept 1 may be acceptable, first for that to be so, they must define some interim program to ensure that appropriate standards are being retained & that reasonable protection is afforded.

KWS