

Houston
Lighting
& Power
Company

Electric Tower
P.O. Box 1700
Houston, Texas 77001

8005150119

April 2, 1980

ST-HL-AE-441
SFN: C-0570

Mr. W. C. Seidle, Chief
Reactor Construction & Engineering
Support Branch
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012

SUBJECT: SOUTH TEXAS PROJECT ELECTRIC GENERATING STATION
RESPONSE TO NRC INSPECTION FINDING
DOCKET NOS. 50-498/79-16 AND 50-499/79-16

Dear Mr. Seidle:

The following is the additional information you requested on the item of noncompliance identified in IE Inspection Report Nos. 50-498/79-16 and 50-499/79-16, and addressed in your letter of March 3, 1980.

Failure to Include Appropriate Quantitative or Qualitative Acceptance Criteria in Instructions, Procedures, or Drawings

Corrective Action

The Brown & Root Quality Construction Procedure A040KPCCP-3 has been revised to state that no standing water will be allowed on construction joints.

Recurrence Control


Procedural compliance shall be ensured through preplanning meetings and scheduled surveillance activities. Training has been scheduled to inform affected personnel of the changes.

Mr. Seidle
April 2, 1980
Page Two

Date Action Will Be Completed

All retraining of affected personnel shall be completed
by April 11, 1980.

Very truly yours,



E. A. Turner, Vice President
Power Plant Construction
& Technical Services

EAT:rka

cc: Messrs. G. W. Oprea, Jr.
M. L. Borchelt (CPL)
R. L. Range (CPL)
J. B. Poston (CPS)
A. vonRosenberg (CPS)
R. L. Hancock (COA)
M. C. Nitcholas (COA)
H. R. Dean
R. L. Waldrop
C. L. McNeese
D. G. Barker
R. A. Frazar
W. N. Phillips
L. D. Wilson
G. B. Painter
M. D. Schwarz (Baker & Botts)
C. G. Thrash (Baker & Botts)
H. S. Phillips (NRC)
J. R. Geurts (B&R)
C. W. Vincent (B&R)
STP RMS