



CONNECTICUT YANKEE ATOMIC POWER COMPANY

HADDAM NECK PLANT

RR #1, BOX 127E, EAST HAMPTON, CONN. 06424

May 12, 1980

CYH 80-080

U. S. Nuclear Regulatory Commission
Region 1
Office of Inspection and Enforcement
631 Park Avenue
King of Prussia, Pennsylvania 19406

Attn: Mr. Boyce Grier,
Director

Reference: Facility Operating License No. DPR-61
Docket No. 50-213
ETS-NR/50-213/80-02 (10 Day Report)

Dear Mr. Grier:

On May 4, 1980, while in the process of slurring an ion exchanger the instantaneous release rate limit for gaseous discharges as specified in Environmental Technical Specifications, Section 2.4.3.1 was exceeded. A prompt report was made to your office on May 4, 1980.

A written report containing a detailed description as required by Environmental Technical Specifications 5.6.2.a(1) is attached.

Very truly yours,

Richard H. Graves
Station Superintendent

RHG:JML/jhb
Attachment

cc: Dir., Office of Nuclear Reactor Regulation, Washington, D. C. (17)
USNRC, c/o Document Management Branch, Washington, D. C.